

MATERIAL SAFETY DATA SHEET

Laminated Veneer Lumber Products (Untreated)

Date of Issue: October 2002

STATEMENT OF HAZARDOUS NATURE: Not classified as hazardous according to criteria of Worksafe Australia.

futurebuild (a division of Carter Holt Harvey Wood Products)

ACN 002 993 106

22 Prospect Street

P O Box 425

Box Hill VIC 3128

Australia

Telephone: +61 3 9258 7600

Facsimile: +61 3 9258 7629

IMPORTANT NOTICE: This Material Safety Data Sheet (MSDS) is written by futurebuild in accordance with Worksafe Australia and OSH New Zealand Guidelines. As such, the information contained herein must not be altered, deleted or added to. futurebuild will issue a new MSDS when there is a change in product specifications and/or the guidelines or regulations. futurebuild will not accept responsibility for changes made to its MSDS in content by any other person.

IDENTIFICATION

Product Names: Hyspan - structural laminated veneer lumber (LVL) to AS/NZS4357
Hychord - structural LVL to AS/NZS4357
Hyplank - structural LVL to AS/NZS4357
Truform - structural LVL to AS/NZS4357
Hybeam - structural ljoists to AS/NZS 2269 and AS/NZS4357
Edgeform - non-structural LVL

Manufacturer's Product Code: Not applicable

UN Number: None allocated

Dangerous Goods Class & Subsidiary Risk: None allocated

Hazchem Code: None allocated

Poisons Schedule Number: None allocated

Use: Residential, commercial, and industrial construction, and/or general purpose building material.

Physical Description / Properties

Appearance:

The products are manufactured as pressed boards ranging in thickness from 3mm to 90mm. These boards are ripped into strips between 47 and 1200 mm wide to form lineal wood components. Hybeam consists of solid LVL flanges bonded to a plywood web. All products are made from *Pinus radiata* wood veneers bonded together with resin.

Odour:

No distinctive odour. Newly manufactured LVL products and freshly machined surfaces tend to have the odour of the wood species from which the LVL is manufactured.

Boiling Point (°C): Not applicable
Melting Point (°C): Not applicable
Vapour Pressure: Not applicable
Solubility in Water: Highly insoluble
Flashpoint: Not applicable

Specific Gravity: 0.50-1.00
Flammability in air: Fine airborne wood dust, generated when the product is machined, can ignite spontaneously.
Auto Ignition Temperature: >200°C

Ingredients:

Substance/Chemical Entity	CAS NO.	Proportion by weight
Wood veneer	None	>92%
Phenol formaldehyde resin	40798-65-0	<8%

Note: The ingredients are bonded together under heat and pressure. The process cures the resin. However, small amounts of formaldehyde may be released from the finished product. In newly manufactured LVL, formaldehyde emission has been measured in the range 0.03-0.05ppm using the large scale chamber test. Emissions reduce to lower levels in service.

Coated Truform, Edgeform and Hychord have the following additional ingredients in a water based acrylic paint surface layer:

Substance/Chemical Entity	CAS NO.	Proportion by weight
Water based acrylic co-polymer latex colour pigments;	None	0.06% to 0.08%
Lead free organic unregulated additives, thickeners, unspecified	None None	< 0.03% trace

HEALTH HAZARD INFORMATION

Health Effects

This product, in its natural form, is not classified as hazardous. However, handling edges and surfaces may cause splinters. The known health effects of the constituents of LVL are as follows:

Wood Dust:

The main health effects relating to this product result from prolonged exposure to fine wood dust generated by further processing. When the products are machined (sawn, sanded, drilled, routed, planed, etc) wood dust is produced. Wood dust or splinters may cause irritation of the nose, throat, eyes and skin. Wood dust may also be a sensitiser, and some people may develop allergic dermatitis or asthma. Inhalation of wood dust may increase the risk of nasal and paranasal sinus cancers. **Exposure to the wood dust produced from machining the products may result in the following health effects:**

Acute:

Swallowed Unlikely to occur, but swallowing the wood dust may result in abdominal discomfort.
Eye The wood dust may be irritating to the eyes causing discomfort and redness.
Skin The wood dust may irritate the skin, resulting in itching and occasionally a red rash. Allergic contact dermatitis may occur.
Inhaled The wood dust may irritate the throat and lungs especially in people with upper respiratory tract or chest complaints. Asthma may occur.

Chronic:

Repeated exposures to uncontrolled wood dust from these products over many years may increase the risk of allergies, dermatitis, asthma or chronic nose or throat irritation in some people. The risk of nasal or para nasal sinus cancers may also be increased. If the work practices noted in this MSDS are followed, no chronic health effects are anticipated.

First Aid

Swallowed: Drink a glass of water
Eye: Remove contact lenses, flush with flowing water for at least 15 minutes, and if symptoms persist seek immediate medical attention.
Skin: Wash with mild soap and running water
Inhaled: Remove to fresh air. If recovery is not rapid seek medical assistance.

Advice to Doctor: Treat symptomatically.

Phenol formaldehyde resin

In the finished product, the cured resin is inert and not likely to contribute to health effects.

Formaldehyde emission

Formaldehyde gas is irritating to the nose and throat, eyes and skin. It is recommended that storage areas be well ventilated to avoid any irritating effects of a build-up of formaldehyde.

In well ventilated storage areas and work places utilising these products the concentration of formaldehyde in the air will not exceed the World Health Organisation standard of 0.1 ppm for the general environment and it will be well below the occupational Exposure Standard of 1.0 ppm on a time weighted average (TWA). Sealing veneer products with paint, varnish or other surface finishes further reduces emissions from the boards.

The International Agency for Research on Cancer (IARC) assessed formaldehyde in 1982 as Group 2A: - possibly carcinogenic to humans - on the basis of evidence that inhalation of formaldehyde gas caused nasal cancer in experiments with rats. In the experiments, groups of rats were exposed to formaldehyde for six hours a day, five days a week for up to two years at concentrations of 0, 2.0, 5.6 and 14.3 ppm. Fifty percent of those exposed at 14.3 ppm, one percent exposed to 5.6 ppm, but none exposed to 2.0 or 0 ppm developed nasal cancers.

There have been more than thirty epidemiological studies involving over 150,000 people occupationally exposed to formaldehyde. These, and studies of behaviour to toxicity, indicate that exposure to formaldehyde below the occupational Exposure Standard of 1 ppm TWA (time weighted average) will not result in an increased risk of cavity cancers in humans.

As veneer products have emission levels of 0.03 to 0.05 ppm, well below the WHO recommended level of 0.1 ppm, under reasonably foreseeable circumstances it is unlikely that the presence of traces of formaldehyde in the product poses a health risk.

Acrylic paint coating

There are no known additional health effects attributable to the coatings on Truform, Edgeform and Hychord. The coating is a normal lead free acrylic house paint in the dried, applied form and in rework of the product should be treated as for the wood dust above.

The coating is not classified as hazardous according to Worksafe Australia Criteria.

PRECAUTIONS FOR USE

Exposure Standards:

Exposure standards for softwood (e.g. pine) dust and formaldehyde are:

	OSH New Zealand	Worksafe Australia
Wood dust:	5 mg/m ³ time-weighted average (TWA)	5 mg/m ³ time-weighted average (TWA) 10 mg/m ³ short term exposure limit (STEL) Wood dust is also listed as a sensitiser and the Exposure Standard is under review
Formaldehyde	1.0 ppm (1.2 mg/m ³) time-weighted average (TWA) 2.0 ppm (2.5 mg/m ³) short term exposure limit (STEL)	1.0 ppm (1.2 mg/m ³) time-weighted average (TWA) 2.0 ppm (2.5 mg/m ³) short term exposure limit (STEL)

In the interests of maintaining a safe working environment, it is recommended that workplace exposures to wood dust should not exceed 1.0 mg/m³ TWA.

Engineering Controls:

All work with these products should be carried out in such a way as to minimise the generation of wood dust.

Under factory conditions, machining should be done with equipment fitted with exhaust devices capable of removing wood dust at the source. Hand power tools should be fitted with dust bags.

Work areas should be well ventilated. They should be cleaned at least daily, and wood dust should be removed by vacuum cleaning or by wet sweeping.

Skin Protection:

Wear loose, comfortable clothing. Long sleeved shirts, trousers and comfortable work gloves (AS2161) should be worn if skin irritation occurs, and to minimise the risk of splinters.

After handling boards, wash with mild soap and water. Do not scratch or rub the skin if it becomes irritated.

Wash work clothes regularly and if possible separate from other clothes.

Respiratory Protection:

If wood dust exposures are not controlled when machining (sawing, routing, planing, drilling, sanding, etc.) a class P1 or P2 replaceable filter or disposable face piece respirator should be worn. Respirators should comply with AS/NZ1716, and be selected, used and maintained in accordance with AS/NZS1715.

Eye Protection:

Safety glasses or non fogging goggles (AS/NZS1337) should be worn when machining.

Flammability:

These boards are combustible but difficult to ignite.
Avoid a build-up of wood dust and keep all storage work areas well ventilated.
Avoid sources of radiant heat and flame, and avoid sparks and sources of ignition in all electrical equipment, including dust extraction equipment.
People must not smoke in storage or work areas.

SAFE HANDLING INFORMATION

Storage and Transport:

Products should be stored in well ventilated areas away from sources of heat, flames or sparks.
No special transport requirements are considered necessary.

Spills and Disposals:

Off-cuts and general waste material should be placed in containers and disposed of at approved landfill sites, or disposed of in an approved furnace or incinerator, in accordance with disposal authority guidelines.
Wood dust should be cleaned up by vacuuming or wet sweeping.

Fire/Explosion Hazard:

Early fire hazard properties as determined in accordance with AS1530 Part 3.

Ignitability Index	14
Spread of Flame Index	7
Heat Evolved Index	7
Smoke Developed Index	3

Burning or smouldering products or wood dust can generate carbon dioxide and other pyrolysis products typical of burning organic material. Dry wood dust in high concentrations can be explosive. Use water or dry chemical fire extinguishers.

Smoking:

Storage and work areas should be smoke free

CONTACT POINT:

NEW ZEALAND
futurebuild
Private Bag 92-106
Auckland
New Zealand
Phone: 64 9 261 2000
Facsimile: 64 9 261 1841

AUSTRALIA
futurebuild
P O Box 425, Box Hill
Victoria 3128
Australia
61 3 9258 7600
61 3 9258 7629

Whilst the information contained in this document is based on data which, to the best of our knowledge, was accurate and reliable at the time of preparation, no responsibility can be accepted by us for errors and omissions. The provision of this information should not be construed as a recommendation to use any of our products in violation of any patent rights or in breach of any statute or regulation. Users are advised to make their own determination as to the suitability of this information in relation to their particular purposes and specific circumstances. Since the information contained in this document may be applied under conditions beyond our control, no responsibility can be accepted by us for any loss or damage caused by any person acting or refraining from action as a result of this information.

This Material Safety Data Sheet (Issue Date: October 2002) has been independently reviewed by Chemwatch.